


TECHNICAL DATA SHEET

RAY



Gloves are meant for protection against mechanical risks.

LEVELS OF PROTECTION:

EN 388	MECHANICAL RISKS	
	abrasion resistance:	3
	cut resistance:	1
\setminus	tear resistance:	2
\sim	puncture resistance:	1
	cut resistance (TDM):	Х

This personal protective equipment is in conformity with these harmonized European Standards:

EN 420:2003+A1:2009 : Protective gloves- general requirements EN 388:2016 : Protective gloves against mechanical risks

Certified by notified body no 2369 (VIPO a.s., Slovakia), Certificate 00254/111/1/2019.

Pairs in carton:	120
Carton weight:	14, 16, 18 kg
Carton size:	0,062 m ³
Polybag packing (pairs):	12

Store in dry and dark enviroment. Clean dirt with brush. Gloves can not be washed or cleaned chemically. Do not expose gloves to heat of radiation, organic solvents and their fumes, lubricants, grease, mineral oils, caustics and wat.

Warning: Gloves can not be used in enviroment where there is risk of glove being catched by moving parts of machine.

ARDON SAFETY s. r. o. Tržní 2902/14, Přerov I - Město Tel.: 581 250 061 www.ardon.cz